Manhole In	spection Summary	Manhole # S17G007MH		
Printed On: 8/20)/2009	Page 1 of 4		
Inspection	☐ Is Incomplete Rating: 3) Fair			
Record Plat: 17	7G Node: 007 Status: Found	Insp Date: 5/14/09 12:06 PM		
Incomplete Cor	nments	Crew: ADS2 Inspector: ADS3 Firm: ADS		
Location	Address: 123 WARWICK AVE	Cross Street: LEXINGTON ST		
Manhole	Type: Junction Location: Alley	Ground Conditions: Dry		
	☐ Prev. Rehab Weather: Dry	Subject To Ponding: None		
Comments	s 36IN PIPES, NO SILT, DOF - 18IN, RTC - @12-10.68 @6-10.67			
Cover	Shape: Circular Diameter: 25. ((in.) Length: (in.) Dist A/B Grade: 0 (in.)		
	Type: Sanitary Condition: Soun	d Cover Material: Cast Iron		
Properties:		☐ Water Tight Insert		
Frame	Offset: 1 (in.) Condition: 🗸 Sound	☐ Cracked ☐ Leaks		
Chimney / Fra	ame Adjustment 🗸 Exists Material: Brick	Parged Height: 4 (in.)		
Condition: ☐ Sound ✓ Cracked ☐ Root Intrusion ✓ Loose Brick ☐ Deteriorated				
Infiltration:	✓ None ☐ Joint ☐ Cracks ☐ Mortar	☐ Roots ☐ Wall		
Corbel	Material: Brick	d Type: Concentric/Eccentric		
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated			
Infiltration:	✓ None ☐ Joint ☐ Cracks ☐ Morta	ar □ Roots □ Wall		
Barrel	Material: Concrete Parge	d		
Shape: Circular Diameter: 46 (in.) Length: (in.)				
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion	☐ Loose Brick ☐ Deteriorated		
Infiltration:	✓ None ☐ Joint ☐ Cracks ☐ Morta	ar		
Bench	☐ Exists Material:	☐ Parged		
Condition:	☐ Sound ☐ Cracked ☐ Root Intrusion	☐ Deteriorated ☐ Leaks ☐ Debris		
Channel	Material: Concrete Parge	d		
Channel E	xposure: Fully Open Junc Dist: 0	nearest .5 ft. Azimuth:		
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion	☐ Deteriorated ☐ Leaks ☐ Debris		
Steps Count: 7 Missing: 0 Corroded				
Surcharge	Evidence Of Surcharge Depth: (f	t.) 🗸 Active Surcharge Present		

Manhole Inspection Summary

Manhole # S17G__007MH

Printed On: 8/20/2009 Page 2 of 4


Location View



Top View



Defect 2



Top View



Defect 3



CORRODED STEPS

Defect 1



FRAME OFFSET

Manhole Inspection Summary

Manhole # S17G 007MH

Printed On: 8/20/2009 Page 3 of 4

36 in. Circular Gravity Sewer Pipe Out @ 12 O'Clock





Pipe Height:

(in.) Direct

Pipe Material: Concrete

☐ Pipe Lined

Invert Depth: 13.68 (ft.) Flow Characteristics: Fast

Deposits: ✓ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease

Silt Depth:

(in.) Deposits Extent:

Infiltration: None


Pipe Seal Cond: Sound

Drop: None

Connects To: Manhole

Possible Illicit Connection

36 in. Circular Gravity Sewer Pipe In @ 6 O'Clock





Pipe Height:

(in.) Direct

Pipe Material: Concrete

☐ Pipe Lined

Invert Depth: 13.67 (ft.) Flow Characteristics: Fast

Silt Depth:

(in.) Deposits Extent:

Infiltration: None

Pipe Seal Cond: Sound

Drop:	None	

Connects To: Manhole

Possible Illicit Connection

Manhole Inspection Summary

Manhole # S17G__007MH

9 O'Clock Inflow

Printed On: 8/20/2009 Page 4 of 4

8 in. Circular Gravity Sewer Pipe In @ 9 O'Clock



Pipe Height: (in.) D	irect	Drop: None
Pipe Material: Clay	☐ Pipe Lined	
nvert Depth: 11.63 (ft.) F	Flow Characteristics: Fast	
Deposits: 🗸 None 🗌 Mu	ud □ Sludge □ Debris □ Grease	
Silt Depth: (in.)	Deposits Extent:	Connects To: Manhole
nfiltration: None	Pipe Seal Cond: Sound	Possible Illicit Connection